Defect Pareto Chart



- This chart shows the biggest problem was "Part Damage on Thru Hole Parts"

SYMETRICS INDUSTRIES