

# Failure Analysis Report (FAR)

## FAR

- Customer
- Description of product
- Failure
- Cause
- Troubleshooting
- Parts Reworked

### Symetrics Industries LLC Failure Analysis Report (FAR)

FAR Number: 681		Preparer: grh	
Customer:		PO-Line Item:	e65886-t71 rev1 bid 2893
Assembly:	6445179	Description:	LTAS PROCESSOR S/N: 221
Date Released:	2/1/07	Date Due:	3/21/07
		Date Completed:	2/9/07
DMR:		Project:	4560-1-1547
		Detected At:	Customer
Failure:	CCA HAS BENT PINS, WEDGE LOCKS MISSINGPIECES/BENT PINS		
Cause:	CCA HAS BENT PINS, WEDGE LOCKS MISSINGPIECES/BENT PINS		
Troubleshooting main assembly:	REPLACE P1, RIGHT AND LEFT WEDGELOCKS, AND C117		
Comments:			
Parts on Main Assembly:	Part Reworked:	M55302/193B 1524	CONECTOR
	Ref Des:	P1	
	Part Reworked:	13494837-3	WEDGELOCK L
	Ref Des:		
	Part Reworked:	13494837-4	WEDGELOCK R
	Ref Des:		
	Part Reworked:	M39014/22-3794	CAP
	Ref Des:	C117	
Subassemblies:			
Subassembly:		Description:	
		S/N:	
Troubleshooting:			
Part Reworked:			
Ref Des:			

